



## **SURFACE PREPARATION GUIDE FOR ADHESIVES, SEALANTS, AND COATINGS**

For most applications, good bonding may be obtained by the following surface preparation: solvent degreasing with trichloroethylene or solvent wash with acetone or methyl ethyl ketone; mechanical abrasion either by sandblasting or roughing with medium grit emery paper; additional solvent degreasing or solvent wash to remove grit contamination.

However, for optimum adhesion to many substrates, a chemical etch is the preferred surface preparation. The following guide includes the more commonly encountered surfaces :

### **Substrate Procedure**

#### **Aluminum, Aluminum Alloys**

1. Degrease or solvent wash.
2. Acid etch for 5-10 minutes at 70° C in the following solution:

1 part by weight – sodium dichromate  
30 parts by weight – distilled water  
10 parts by weight – concentrated sulfuric acid

3. Rinse the metal thoroughly with clear running water and dry thoroughly at or below 65° C.

#### **Cast Iron**

1. Degrease
2. Abrade
3. Degrease again.

NB Because of contamination inherent in cast iron it may be necessary to prebake the cast iron above the bonding temperature before final degreasing.

#### **Concrete**

1. Remove oily contamination by commercial concentrated degreasing compound using a stiff brush.
2. Acid etch with a 15% solution of hydrochloric acid (muriatic) using a stiff brush.
3. Allow surface to dry thoroughly.

#### **Copper, Copper Alloys (Brass)**

1. Degrease
2. Immerse in the following solution for 1-2 minutes at room temperature:

115 parts by weight – water  
24 parts by weight - concentrated nitric acid  
12 parts by weight - 42% ferric chloride solution

3. Rinse thoroughly with clear running water..
4. Force-air dry at 60°-65° C.

#### **Glass**

1. Degrease.
2. Frost surface, either by sandblasting (fine grit) or wet sanding (emery).
3. Water rinse.
4. Solvent wash.

Please note that the information contained within this bulletin is for guidance only and is by no means an offer of guarantee of performance. Trials must be performed to ensure suitability.



### **Magnesium, Magnesium Alloys**

1. Degrease 10 minutes in trichlorethylene.
2. Immerse in the following solution for 10 minutes at 75°-85° C:

250 parts by weight – water  
2 parts by weight – sodium metasilicate  
1 part by weight – tetrasodium pyrophosphate  
1 part by weight – Nacconol NR (National Aniline)

3. Rinse in distilled water at 75°-85° C.
4. Immerse in the following solution for 10 minutes at 65° C

160 parts by weight – distilled water  
40 parts by weight – chromium trioxide

5. Force - air dry for 10 minutes at 75° C

### **Nickel**

1. Degrease
2. Acid etch for 5 seconds in concentrated nitric acid.
3. Rinse thoroughly in warm water.
4. Force-air dry at 60°-65° C.

### **Steel**

1. Degrease
2. Immerse in the following solution for 15 minutes at 73° C:

8 parts by weight – concentrated hydrochloric acid  
8 parts by weight – concentrated sulfuric acid  
84 parts by weight – concentrated nitric acid

3. Rinse with warm water and descale if necessary.
4. Force-air dry at 70° C.

### **Stainless Steel**

1. Degrease.
2. Immerse in the following solution for 15 minutes at 25° C:

35 parts by volume – saturated sodium dichromate solution  
100 parts by volume – concentrated sulfuric acid.


3. Force-air dry at or below 65° C

### **Titanium, Titanium Alloys**

1. Degrease 10 minutes in trichloroethylene.
2. Immerse in the following solution for 15 minutes at 50° C:

35 parts by volume – saturated sodium dichromate solution.  
100 parts by volume – concentrated sulfuric acid.

Please note that the information contained within this bulletin is for guidance only and is by no means an offer of guarantee of performance. Trials must be performed to ensure suitability.



3. Rinse in distilled water heated to 70° C.
4. Force-air dry for 10 minutes at 35° C.

### **Zinc and Galvanized Metals**

1. Degrease.
2. Immerse in the following solution for 3 minutes at 25° C:

80 parts by weight – distilled water  
20 parts by weight – concentrated hydrochloric acid

3. Rinse thoroughly in cold running water.
4. Force-air dry for 15 minutes at 70° C.

**CAUTION: In preparing acid etch solutions, always slowly add acid to water, while stirring, to dissipate heat of solution.**

Methyl Ethyl Ketone (MEK) and Acetone are flammable solvents (Flashpoint MEK = 23° F and Flashpoint Acetone = 8° F). When using MEK or Acetone, handle with extreme care. Remove all ignition sources; sparks, flames, or hot surfaces can ignite these materials. These solvents and chlorinated solvents, such as Trichloroethylene, 1,1,1-Trichlorethane, and Methylene Chloride, all pose substantial risks to the nervous system, liver, and kidneys. Do not inhale vapors. Do not let these types of materials contact the skin. Use appropriate controls or personal protection equipment when handling these materials. Always read the Material Safety Data Sheets before using any hazardous materials.

NOTE: Etched parts should always be used immediately. Do not expose to air longer than necessary.